Rosemary Inn, Summerie Cabin (Building No. 384) Olympic National Park Barner Point, Lake Crescent Port Angeles Vicinity Clallam County Washington HABS No. WA-185-L

HARS WASH 5-POAN!

سلن

FHC/ITX:RAFHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Building Survey
National Park Service
Western Region
Department of the Interior
San Francisco, California 94107

NATIONAL PARK SERVICE Department of the Interior

HISTORIC AMERICAN BUILDING SURVEY ARCHITECTURAL DATA FORM

	P			
STATE			TOWN OR VICINITY Approximately 20 miles southwest of	
WASHINGTON	CLALLAM		Port Angeles	
HISTORIC NAME OF STRUCTURE (include source for name)			HABS NO.	
Rosemary Inn, "Summerie" Cabin WA-185-L				WA-185-L
SECONDARY OR COMMON NAMES OF STRUCTURE				
ଅଧୀdg. No. 384				
COMPLETE ADDRESS (for rural sites describe location) Barnes Point, south shore of Lake Crescent, north side of Hwy 101, approximately 20 miles from Port Angeles, in Olympic National Park.				
DATE OF CONSTRUCTION (include source) ARCHITECT(S) (include source) Builder arid Craftsman:				de source)
c.1920 (Historic Building Inventory)		John Daum (HRS, 1983)		
SIGNIFICANCE (architectural and historical, include original use of structure)				
This cabin was constructed as an integral part of the Rosemary Inn Complex. It contributes to the overall character of the rustic, picturesque resort ensemble and possesses integrity				
of design, materials, workmanship, location, setting, feeling and association.				
STYLE (if appropriate)				
Craftsman-style cabin				
MATERIAL OF CONSTRUCTION (include structural systems)				
Wood-frame construction set on 6 x 6 posts on concrete piers and blocks				
SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable)				
Irregular: 14' x 20' with a 6' x 8' extension on east				
EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with projecting cross gable				
lentiance porch on west racade, extended eaves and exposed rafters; porch supported by beeled				
logs and log braces set on boxed posts; log and bark "stickwork" beneath porch gable; clap-				
board siding with board and battens above and shingles above that at gable ends; hip-roofed entry overhang supported by braces on south; 4-over-1 casement and multi-paned hinged sash;				
Inlain fascia and corner heards: concrete chimney on east facade has decorative heart and				
INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) arrow motif, capped with stones.				
Painted floor boards; painted vertical wood wainscotting on walls with painted horizontal				
wood boards above; original par	tition divides	Spaci	e into two s	leeping rooms with separate
entrys. •				
MAJOR ALTERATIONS AND ADDITIONS, WITH DATES				
Asbestos shingles on bathroom addition (east), n.d.				
PRESENT CONDITION AND USE				
Fair; Vacant				
OTHER INFORMATION AS APPROPRIATE				
SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979				
Historic Resource Study, 1983				
Historic Building Inventory, 1983				
COMPILER, AFFILIATION	·	·····		DATE
Gretchen A. Luxenberg, National Park Service				July, 1988

